

For the information of Surveyors and the Committee only.

Received at _____ Office, _____ 19

Lloyd's Register of Shipping.

(Report on Machinery, No. _____ Port _____)

No. 1399. ENGINE FORGINGS OR CASTINGS. ~~XXXXXXXXXX~~

I have to report that the Forgings ~~or Castings~~, as herein described, manufactured by Messrs. Walter Somers Ltd., of Halesowen, order 4719/39 for the Engines No. ~~being constructed by~~ of Messrs. Parsons Marine ~~or~~ Steam Turbine Co. Ltd., for the Ship No. *Hopestar*, being built by _____ of _____

have been inspected by me as set forth below, and found to be, so far as can be seen, sound and free from defects. These have been despatched to Newcastle-on-Tyne.

Forgings of ~~XXXXXXXXXX~~

A.D. Buchanan

Lloyd's
No. 1394.
B. 7/8/40.

Birmingham. 8/8/40.

	XXXXXXXXXX	THRUST SHAFT.	INTERMEDIATE SHAFT.	TUBE SHAFT.
	1 Thrust Collar. XXXXXXXXXX			SCREW SHAFT.
	Steel.			
	Forged.			
	Yes.			
	17" O/D., 6" Hole.			
Forgings	0-1-2-16.			
Castings				
Condition	Rough Machined.			
RESULTS.	372.			
Tensile.				
sq. in. ...	31.08			
sq. in. ...	18.36			
per cent inches ...	35.0			
area % ...	56.0			
ing Test...	180 WF.			
Inspected	29/7/40, 2/8/40 & 7/8/40.			


PARTICULARS OF OTHER TESTS APPLIED TO CASTINGS:-

examined finished & found satisfactory - stamped as above, and - H.C.F. 11.7.41.

H.G. Forster, Newcastle-on-Tyne, Birmingham. 11.7.41

Included in fee shown any chargeable) on Report F.1398 To be paid at

wrought iron, state whether piled bars or scrap. If of steel, state whether made by the Open Hearth process



W1013-0271

TUE 1 APR 1941

Committee's Minute

Lloyd's Register Foundation

rs of Classification
 ely as in Register
 RACTER.
 ecial Survey.
 & Survey and of
 eal Surveys.
 1
 february
 12.39
 board (if assign
 Ship and now v
 whom? Mess
 caused
 been ab
 from B
 ide to si
 nately see
 No. 3 hold
 engine ro
 and from
 on stab
 Items :-
 temporary
 detailed.
 Copper, or Y.M.
 (State if o
 When fitted, M
 Boats
 Masts, Yards,
 Condition, how
 (State if w
 Equipment lett
 Anchors, No. of
 Cables (State
 ,, length
 (on b
 ,, Rule leng
 Chain Locker
 Hawsers & Wa
 Standing and R
 Sails
 sel in the Regis
 remain as clas
 repairs
 is four