

Lifting Sunken Craft

Fire or Discharge

is no fouling or damage to either the propellor or shafting.

Yours faithfully,

Key Bolters?

1m.11.36.

5 E

25 OCT 1939

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME

"HOPESTAR".

Fre.

1202.

Rpt.

No.

Rpt 9

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

DAMAGE=&=WEAR AND TEAR.

Main injection gear casing opened out and examined, thoroughly
celaned out and the teeth of the secondary pinion dressed up.

Adjustments made to the thrust block.

It is submitted the vessel is eligible to remain as classed without
record of Survey as recommended.

25.10.39.

W1013-0291

This Certificate is issued upon the terms of the Rules and Regulations.

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

(Cert. B1.)—10m.8.38. (MADE IN ENGLAND.)

(Rpt. 10.) 1m.1.36.

Attach to Report No 1202

© 2020

Lloyd's Register Foundation

Engineer Surveyor to Lloyd's

8.38.—Transfer

Surveyors are req

Special Damage or Repair Fee (if any).....

(per Section 20.)

Travelling expenses (if chargeable).....

£

8.18

Received by me,

19

Committee's Minute

FRI. 27 OCT 1939