

Was a damage report made by anyone else? If so, by whom?

3m,9,35.

11

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

- 1 JAN 1938

VESSEL'S NAME

HOPESTAR

Rpt.

Nwc.

No.

95759

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/6/92.)


Nature of Survey

The Newcastle-on-Tyne Surveyors report this vessel placed in

dry dock, bottom cleaned and coated, ~~repairs to~~
and minor repairs effected.

It is submitted the vessel appears worthy to remain as
classed with record of survey 12, 37 as recommended.

100 A1
with freeboard
12, 37 Nwc.



© 2020

Lloyd's Register
Foundation

W1013-0312

this survey, thus, for example:—to remain as now classed in the Register Book without fresh record of survey, "to remain as classed and to survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND24, &c."

This vessel is eligible, in my opinion, to remain as
classed and have record of survey 12, 37