

Chief Ship Surveyor

Received from Chief Ship Surveyor

14 OCT 1936

NAME "HOPESTAR" / Rpt. Bdx. No. 4819

arks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

urvey


The Bordeaux Surveyor reports the ship examined as far as practicable afloat after grounding.

Soundings taken and no leakage found.

The Surveyor, however, recommends the vessel be placed in dry dock for further examination of the bottom at the first convenient opportunity.

It is submitted action be deferred and the Owners informed of the Surveyor's recommendation.

Insert in S.L.



14.10.36 2020

Lloyd's Register
Foundation