

4 E

12 OCT 1936

Engineer Surveyor

Received from Chief Engineer Surveyor

ME "HOPESTAR"

Rpt. Bdx

No. 4819

of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee Report, 24/5/32.

REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH GROUNDING.

All furnaces examined, a number of plain tubes expanded, feed check valves repaired and engines generally examined.

It is submitted the vessel is eligible to remain as classed without fresh record of survey subject to the machinery being further examined at the first convenient opportunity.

W1013-0332

© 2020

Lloyd's Register
Foundation