


RD REPORT on the

Copectar

It is submitted the Bros. Lemp
be informed it is assumed that 2 Tarpanes
are fitted to the hatchways referred to
in Item 3 of Rpt @ 11(a), but he
should state if this assumption is
correct.

Job
21/3/40



© 2020

Lloyd's Register
Foundation

W1014-0042