

COPY

KNOX CARE LLOYDS REGISTER
50 BOULEVARDFOUAD 1
PORT SAID

(18.6.42)

72453 OWNERS DESIRE RECLASSIFICATION WHILST REPAIRING ADEN
AND DRYDOCKING MASSAWA STOP SECOND NUMBER THREE WILL BE
REQUIRED BUT IF FULL REQUIREMENTS IMPRACTICABLE ARRANGEMENTS
SHOULD BE MADE FOR ABRIDGED REPAIRS TO RENDER VESSEL ELIGIBLE
FOR EXAMINED RECORD FOR TWELVE MONTHS STOP BUCHAN DUE LEAVE
MID JULY. AND FULLICK ACTING STOP IN VIEW NATURE SURVEY REQUIRED
CABLE WHAT ARRANGEMENTS YOU CAN SUGGEST FOR CARRYING OUT
REQUISITE SURVEY ALSO FREEBOARD ASSIGNMENT SURVEY INCLUDING
FULL PARTICULARS REPORTS C11 AND C11(COMP) AND DEEPER LOADING
LLOYDS REGISTER



© 2020

Lloyd's Register
Foundation

W1015-0046