

WOKINGHAM COPY.

Dear Sirs,

6th July 1943


I have to acquaint you that Lloyd's Agents at Suva report that a Load Line Renewal Survey has been held by their Surveyor on the yacht "JOHN WILLIAMS V" in conjunction with the survey for class. The Surveyor states that the Load Line Certificate on board has been endorsed "to remain in force" but I think it well to point out that this certificate was issued in May 1938 under the 1936 Board of Trade Rules and is therefore no longer valid.

Convention Freeboards have not been assigned to the vessel by this Society and I shall be glad if you will endeavour to ascertain and let me know whether these are now desired. If so, full particulars on Rpt CLL and CLL(comp) should be forwarded to this Office and an extract of particulars from the original freeboard report will be sent on application. I may add that the centre of the Load Line disc will not be affected by the re-assignment.

I am, Dear Sirs,
Yours faithfully,

The Surveyors,

Clerk to the Itt



© 2019
Lloyd's Register
Foundation

w 1017 - 0086