

decks, hatches, casings, vents, coamings and windlass  
and steering quadrant (chains and rods to be examined).  
There are two cement boxes in No.1 low hold(s.s.) one being

ment boxes in

, is buckled.

s a prece

s rust sp

tems :-

Copper, or Y.L.  
(State if or

When put

Boats .....

Masts, Yards, &

Condition, how

(State if w

Sails .....

Equipment lett

Anchors, No.

Chain Locker

Cables (State

Cables length.

(on

Cables Rule

Hawser & Wa

Standing and

or Book consequen  
y, 1,24," or "to

tion of

SURVEYOR

TELEPHONE: NO. 23335.



United with  
THE  
BRITISH  
CORPORATION  
REGISTER.

# Lloyd's Register of Shipping,

RECEIVED Laxmi Building,

Ballard Road,

13 FEB 1950

ANSD.....

Dear Sir,

Bombay, 4th FEBRUARY 1950.

S.S. "IRRAWADI".


Referring to Bombay Report No. 9343 on this vessel I beg to advise you that the Owners have now informed us that they have sold this vessel on the 25th January 1950 to Messrs. Khanbhai Esoofbhai of Bombay for breaking up purposes.

I am, Dear Sir,  
Yours faithfully,

*John Rundle*

The Secretary,

L o n d o n.



© 2019

W1017-020

Lloyd's Register  
Foundation



Referred to Mr. Chinneck.

Referred to Mr. Spray

*[Handwritten signature]*

also for Mr. Perris to note.

*[Handwritten in red: "Com to co r R"]*



© 2019

Lloyd's Register  
Foundation

УНИКЕР ПО РАТРИЗЕР ЗАРАД  
ДИДИЛИУС ИМХА  
ДАОВ СРАДЛАВ  
YABWOB

COBY  
1020