

Port belonging to Bombay.

Destined Voyage B. m. local

If Summoned while Building Afloat, or in Dry Dock *Build*

of Decks with flat laid
Tiers of Beams 2.

of Surveyors 12. 11. 13

Received from Chief Surveyors

S NAME Sheelso Lrr awadi

Report

No. 33322

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24.5.92.*)

Survey

1st Aug -

When due

* 100 A-1. (Steel)

1 Dr. (Teak) & 2nd Dr. in hot. hold.

WB = FPT 246 A.P.T. 306

BK $8\frac{1}{4}$. 4 BA. Cem. Lhys a + c.p.

MA
12.11.13

W1017-0206 © 2019

Lloyd's Register

| | |
|--|----------------------------|
| „ | Angles on upper edge |
| „ | Spacing |
| BEAMS, Bridge Deck, Angle, Bulb Angle, Plate, Tee Bulb, or Channel..... | |
| „ | Angles on upper edge |
| „ | Spacing |

| | |
|---|---|
| ” | Tie Plates..... |
| ” | Deck, Material and thickness..... |
| | Forecastle Deck Stringer Plate, b'dth & th'kns |
| ” | Angle on ditto..... |
| ” | Tie Plates |
| | Deck, Material and thickness..... |