

percentage of strength of circ. end seams

plate 64.8
rivets 66.6
plate 85.3

Percentage of strength of circ. intermediate seams

boiler No. 5755.
filers No. 2669.

Made by { Riley Bros.
Richardsons Westgarth & Co.
Davie S B & Repairing Co.


Upl.
Mdb.

Report No. 16583.
13065.

Copies of this Report be forwarded to
the Quebec Surveyors for their guidance and
for completion.

Copy sent
Montreal
17.1.28

Date 22/12/27



Lloyd's Register
Foundation
W1019-0093

Thickness $\frac{24}{32}$ "

Lower back plate: Material Steel

Tensile strength $\frac{26}{32}$ 36

Pitch of stays at wide water space $13\frac{1}{2} \times 8\frac{3}{4}$ "

Are stays fitted with nuts or riveted over