



Lloyd's Register of Shipping.

LLOYD'S REGISTER
RECEIVED
25 APR 1939
ANGL.
LONDON

95, Bothwell Street,

Glasgow, C.2. 24th April, 1939.

Dear Sir,

In reply to your letter of the 22nd instant in regard to Glasgow Report No. 60913 on the Refrigerating Machinery and Appliances of the Steamer "RARANGA", I beg to acquaint you that the Surveyor states that 13 coils of the condenser were tested separately to 2,000 lbs. per square inch in order to find which was defective, and the defective one was blanked off.

It is not the intention of the Owners to renew the defective coil in the near future.

I am, Dear Sir,

Yours faithfully,

P. L. Warlow

Secretary to the
Glasgow Committee.

The Secretary,
LONDON.



© 2020

Lloyd's Register
Foundation

Deferred to J. H. H. H.

R. M.

25 APR 1939

Noted.
Submitted the
asked to state when the
was tested whether it is the
same sentence as that referred to
in Lasan Rept 59626 in which the
stated there more 8 coils in food
condition

26/4/39

for Glo:-



© 2020
Lloyd's Register
Foundation