

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C.3.

22nd April, 1939.

Dear Sir,

With reference to Glasgow Report No.60913 on the refrigerating machinery appliances of the steamer "RARANGA", and to the statement therein that the H.P. condenser coil has been blanked off leaving 12 sound coils, I shall be glad if you will be good enough to enquire of the Surveyors, and let me know, what steps were taken to ascertain that the 12 coils in question were sound, and whether the Owners propose to renew the defective coil which has been shut off.

I am, Dear Sir,

Yours faithfully,

pro Secretary.

The Secretary,
GLASGOW.



© 2020

Lloyd's Register
Foundation

W1019-0202