

AND INLAND TELEGRAMS: " SOMISTO " AUCKLAND

W. RICHARD SMITH,  
SHIP AND ENGINEER SURVEYOR  
TELEPHONES { OFFICE No. 43-163  
{ RESIDENCE 42-492

# Lloyd's Register of Shipping

63 Endean's Buildings.

Queen Street.

Auckland, C.I. N. Z.

THE SECRETARY,

S.

RECEIVED

22 SEP 1948

14th. SEPTEMBER-19 48.

Dear Sir ,

4347. "NARBADA" -

In reply to your classification letter dated 9th. JULY 1948, I am able to confirm that the Port Ford. Boiler end plate adjacent to the centre bottom longitudinal stays was carefully examined by me, and in my opinion the condition was satisfactory on account of the safety factor being well maintained, with due regard to the age of the Boilers.

I might add this boiler has been constantly under my supervision, and I have been satisfied with the conditions found .

Yours faithfully,

.....  
(W. Richard Smith).

SURVEYOR TO LLOYD'S REGISTER OF SHIPPING .

P. E. Clement Esq.  
Secretary.

Special Damage or Repair Fee (If any) ..... £ : :  
(per Sec. 29)

Travelling Expenses (If chargeable) ..... £ : : ✓

Received by me,

19

Lloyd's Register  
Foundation



Referred to Mr. Perris.

HTMS GRANDIR, W  
ROYAUME BELGIQUE DIA 918  
231-24, OFFICE DE  
RECHERCHE 42-24  
LEFEBVRES

quintipe in tainigat a'guat

© 2020

Lloyd's Register  
Foundation

*quintipe in tainigat a'guat*  
*quintipe in tainigat a'guat*

RECEIVED  
10093655

"ADASHAN" 1934



betat vertel noitsolileals tuoy of vldet ni  
priet jtoq edt jadt mltinos of elds ms I, 84el xilut. dss  
lenbutignol motlod ettnes edt of jneos[ba etalo dne telles  
edt noitnigo ym ni dne, em vd benimaxe yllnietso awt aynde  
totsei vletas edt to jnwoos no vtotoxetelisse saw noitlilnno  
edt to ega edt of bzager sub dttw, benietnism flew gnted  
vltatetatos need awt relted aildt bbe jngim I  
edt dttw belietelisse need ewad I dne, noisatvotene ym retnu

yllnietso ettnoy

BS 7/8 la 1/5 W

BS 7/8 la 1/5 W

*li*

SHIPPING

per frame 10.3.3  
vletetud