

If this was not done, state for what reasons?

2 E

27 SEP 1948

by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

Auk.

4382.

REPORT Wln.

No. 4466

L'S NAME NARBADA.

marks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/92.)

Survey COMPLETION OF SPECIAL SURVEY OF ~~ENGINES AND BOILERS FOR S.S. No.~~

This Survey, due 12.47 ~~now~~ partly held 2.48 now completed, and the following repairs carried out (due to wear and tear):-

A number of screw stay nuts in the starboard forward boiler renewed.

Sea connections examined.

It is submitted the vessel is eligible to remain as classed, with notation of B.S. 2.48 as recommended.

MS pt. hd.

W020-0153

27.9.48

some minor repairs effected; Fastenings & Hinge Pins renewed etc. a/c wear.