

by Chief Ship Surveyor 1. 1. 18

Received from Chief Ship Surveyor _____

'S NAME Stl. S.S. "PORT DARWIN". Rpt. Bel. No. 7894

remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

f Survey _____

The Liverpool Surveyors should be informed that the Belfast Surveyors state this vessel is proceeding to their port where the Survey for Classification will be completed, and that to complete the survey the following requires to be done:—

Shelter deck to hose test .

Downton pump and Steam pumps to be tried on bilges.

Hawsers, warps, etc. to examine and Certificate of steel wires to produce.

Some pipes in 'tween deck bunker and in after 'tween decks to be cased in.

Scuppers in Refrigerating Engine Room to fit with screw down valve on upper deck.


Troughs in hospital to be fitted with plugs at upper deck.

W.T.doors on bulkheads 103 & 112 to complete and examine.

Rudder Trunk to hose test.

Boats chocks to complete and Boats to put out.

The Belfast Surveyors should be requested to forward the remainder of the approved plans when they have been received from the Builders.


2. 1. 18

Lt. Bel. & Dir. And.



© 2020

Lloyd's Register
Foundation

W1021-0065