

Rnt. 9

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

Started rivets and plate edges of stem plates in 5th, 6th and 7th strakes below forecastle sheer (P45) electrically welded.

In completion shell satisfactorily hose-tested.

Windlass: Main gear wheel renewed at this time.

Note : The two wheels referred to in S.R.L. N° 106 are in fact the same wheel.

Nothing done at this time in respect of indented plating, set up bottom plating and supply of 15 fms. cable.

ANCHORS.

[illegible]

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

CHAIN CABLES.

[illegible]

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.