

the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

ss Bel.No.1-45.
Examined 8,49.
Fitted for oil

MEMORANDUM

LLOYD'S REGISTER OF SHIPPING, 71, FENCHURCH STREET, LONDON, E.C.3.



29 AUG 1950

(Ref. H.)

Secretary
XXXXXXXXXX at
Name :

LIVERPOOL
T.S.S. "ORBITA."

Date: 21st August 1950

x hps

QUESTION.

ANSWER.

I have to acquaint you that/the validity of present "Examined" notation will expire at the end of the present month, and I shall, therefore, be glad if you will ascertain from the Owners and let me know what arrangements they propose for the completion of the Special Survey. At the same time I think it well to point out that the vessel's Load Line Certificate will expire on the 31st instant and I shall also be glad to be informed of the Owners' intentions in regard to the carrying out of the Freeboard Renewal Survey. I think it well to remind you of the limit regarding the rigging, which requires to be dealt with before the end of this month

Crake


Date: 25th August, 1950.

In reply to enquiry, the Owners write as follows:-

"In reply to your letter of the 22nd August, asking what arrangements we propose making for the Special and Load Line Surveys due shortly, please be advised that on the vessel's return to Liverpool early next month she may be withdrawn from service.

We will advise you of further developments when they arise."

Copy to P



© 2020

W1025-0186

Lloyd's Register Foundation

*Replacement of class B
Incidents in shell plating etc. (15)
See J.R.L.*

board (if assigned
Ship and now ve

by whom ?

used by
tehrway

187

J.S.

130566

*main
mined
after
working*

*ADM.
15.7.50.*