

Chief Surveyors.....

Received from Chief Surveyors.....

SHIP'S NAME SENIORITY

REPORT Gls. No. 74956

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Survey Docking and Damage. When due. --

N O T E D


Subject to permanent repairs to indented shell plates Nos. 3 & 4 in 1st below sheer, Nos. 3 & 4 in 2nd below sheer, No. 4 in 3rd below sheer, C.2 (s.s.f.), and No. 4 in 2nd below sheer (p.s.f.) etc. at next drydocking by 12.50.

CARGO BATTENS NOT FITTED.

Signature 17/2/50.

W1025 - 0227

© 2020



Lloyd's Register
Foundation