

2m,9,49.

21 DEC 1949 5 E

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME

"SAN ROBERTO"

REPORT

Vol.

No. 11118

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/42.)

Nature of Survey

DAMAGE-& WEAR AND TEAR.

Repairs effected to main condenser owing to wastage, and after door renewed.

The furnaces of the starboard boiler were found distorted. One has been faired and the others are considered efficient meantime.


The Surveyor recommends that the main condenser be specially examined at the next Special Survey and that the starboard furnace of starboard boiler be renewed, and the other two furnaces of this boiler specially examined, at the next Boiler Survey.

It is submitted the vessel is eligible to remain as classed with

Record-of-Survey

Subject

as recommended.



© 2020

Lloyd's Register Foundation

W1028-0100

19. 12. 49.

604