

COPY.

23 NOV 1949

Lloyd's Register of Shipping.



Port

FALMOUTH

2nd, November, 1948.

This is to Certify that I have

Partly Starbd. Part
Surveyed the Boiler and Machinery of the steel screw steamer
'SAN ROBERTO' 5890 tons gross of LONDON on account of distorted
furnaces, starbd. boiler and defective main condenser,

and that I have transmitted to the Committee of Lloyd's

Register of Shipping, London, a Report stating that all

recommendations made by me in connection therewith have

been carried out to my satisfaction, and that I have

Recommended that the record of ⁺L.M.C. 3,46 and B.S. 12,48

retained
be ~~made~~ in the Register Book in the case of this vessel; subject to
starbd. furnace, starbd. boiler, being renewed and port and centre
furnaces, starbd. boiler being specially examined at the next
boiler survey. The main condenser to be specially examined at the
Special Survey and as previously recommended.

William

Engineer Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

“While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly
performed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances
to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any
entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its
Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society.”

