



21st April 1950.

RETAIN

WRECK SECTION

No. 587

6,500,10,40.

Received by Chief Ship Surveyor

GB

Received from Chief Ship Surveyor

VESSEL'S NAME

'SOLITAIRE'

REPORT

OsL.

No. 6519

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

P+S 6.46 Corroded

S 4.48 Corroded

As the class of this vessel is expunged from the Register Book with the record of "To be Broken Up" assigned, IT IS SUBMITTED no further action is necessary in this case.

$\frac{30}{9} = 3\frac{1}{3}$

T.S. 8.3/4" (3 lines)

P+S 4.24 — wastage between

P+S 10.28 — Corroded

S 8.30 — Corroded

P+S 7.33 — Corroded

P 7.35 — Corroded

S 3.36 P 7.36 — Bent.

P+S 5.38 — Corroded

P 3.30 Bent

RETAIN

P 5
9 8

© 9.0.80

LR

W1029-0109

Lloyd's Register Foundation

vessel in the Register Book
"to remain as classed and t

without fresh re