

in Donkey Boilers. ✓

If Surveyed Afloat or in Dry Dock. (State name of Dock.)

Last Report No. 106269 Port

Ltr. 4a.

[Thin Copy for attaching to Report.]

NEWCASTLE-ON-TYNE, No. 106444.

Lloyd's Register of Shipping.

NEWCASTLE-ON-TYNE.

Port 9th August, 1949.

United with
THE
BRITISH
CORPORATION
REGISTER.

Dear Sirs

Damage

With reference to the
Survey now being held on the Steamer

"SURREYBROOK"

I beg to inform you that, in consequence of
the condition of this vessel's

Propeller

it will be my duty to recommend to the
Committee that the same be
before the end of

further examined or
repaired

19

as provided for in the Rules, extracts from
which appear on the other side:—the con-
tinuance of the vessel's character in the
Society's Register Book to be subject to the
due fulfilment of this condition.

I am,

Yours faithfully,


H. Matting

Engineer Surveyor to Lloyd's Register.

Williamstown Shipping Co. Ltd.,

To 24 St. Mary Axe, LONDON E.C.3.

2m.11.45



Lloyd's Register
Foundation

W1029-0136