

S.S. "MAMBUKAL".

The circumstances of this case are set forth in the attached endorsement, and it is submitted the Manila Surveyor be informed that it is observed from his letter that the Owners have suggested that the notation respecting the service should be "For Bay and River Service in Sheltered Waters". This notation, however, is not considered to be sufficiently definite and, to comply with the practice of the Committee, should be defined geographically. The Surveyors should therefore discuss the matter further with the Owners.

It should be added that if and when it is desired to transfer the vessel from one similar service to another the class could be modified without delay.

13. 10. 39.



© 2019

Lloyd's Register
Foundation

W103-0057