

1

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME MANCUNIAM Report LIV. No. 115023For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)


Nature of Survey DOCKING When due.....

*Subject to indented plating, framing etc. at forward end (P+S)  
being dealt with at the first convenient opportunity*

*WAG*  
*11.11.40*

In S.R.L

*(Bottom of vessel, clear of E. & B. spaces to specially examine internally  
when in dry dock [cement omitted])*



© 2015  
Lloyd's Register  
Foundation

W103-218