

"WARINA"

Captain Liddle has telephoned Mr. Bryden stating that he is somewhat concerned that Mr. Boyle is unable to recommend the extension of the Load Line Certificate for so short a period as two months, and he will be obliged if Mr. Boyle is able to give any reasons.

Captain Liddle emphasised that he is in no way querying Mr. Boyle's decision as it is known that the British India ^G cannot run her much longer, but he would be pleased to know whether there are any specific reasons or whether it is just that the ship is generally deteriorated.


RL

12th September, 1949.

SHEFFIELD:
Telex 23040

the amount charged.
SERIAL CABLE if
on is not charged for.
ve-named branches.

DON, W.C.2



© 2020

W1030-0156

Lloyd's Register
Foundation