

tests carried out on, the material used in the construction of the boiler be obtained and forwarded to this Office for

NOTE The Rotterdam Surveyors state that "through a misunderstanding this donkey boiler has been delivered without Lloyd's certificate".



© 2020

Lloyd's Register
Foundation

W1031-0019

means of feed and a salinometer cock should be provided

The Surveyors should be asked to reply to

the enquiry contained in the Secretary's letter of the 7th