

Intermediate

Tube

Screw

PUMPING ARRANGEMENT Endorsement.

Shipbuilders: Messrs.

M.V. "TIRIEM" as "LITTLE EGY"

Yard No.

Engineers: Messrs.

(Nº 80027 in R.D.)

Engine No.

Owners: Messrs.

It is submitted that the ^{diagrammatic} plan of ^{oil fuel piping} ~~Pumping~~ Arrangement

merits approval, provided the arrangements be as shown and amended on the plan and the remaining requirements of Section 20 ~~and 21~~ of the Rules (1934-8) be complied with so far as they are applicable.

The Surveyors should be requested to forward plans showing the scantlings of the oil fuel tanks.

Return plan.

Retain copy.

L11/2/35

W.J.F.

© 2020
9/2/35Lloyd's Register
Foundation

E. 4. 1500.0.00. T.

10m 3.33.
wanted not to verifySpecial Damage or Repair Fee (if any) *Repairs* £ 150, -
(per Sec. 29)

Travelling Expenses (if chargeable) £ 20, -

Received by me.

5-4 19 35

Surveyor to Lloyd's