

as per Rule 144 0 Moulded..... 24 0 Top of Floors to Main Deck Beams. 9 2 Power of Engines 64 No. of Tiers of

Dimensions of Ship per Register, Length, 145.0, breadth, 24.0, depth, 9.0, Moulded Depth, ft. 11 ins. 2 Round of

How "Branley"

BOX OAS

Sent to Chief Surveyor 31/8/95

Received from Chief Surveyor

VESSEL'S NAME

S.S. "Penrhyn" Report Gls No. 13905

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

Classification

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed.

+ 100 A.1. "Hul" as recommended.

+ 100 A.1 "Hul."

1 Dk (Hul)

"Well Dk."

W.B. = Cell. D.B. f 67', 72t, F.P.T. 30t.

B.K. 7" Cem.

C. A. J. J. B.
31/8/95



© 2020

Lloyd's Register
Foundation

W1081-0292

Size of Angles on Deck to Web Frames
BRACKET PLATES to Stringers between

3 3 6 3 2 6

LONGITUDINAL

Are the outside Plates doubled two spaces of Frames in length