

the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? No.

Cargo battens

Dankey

119 JUL 1950 4 E

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

S NAME CYGNET. REPORT Gms. No. 24199.

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey ~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

Damage sustained through mine explosion.

Vessel placed in drydock and an preliminary examination carried out. Vessel has been towed to River Tyne where it is intended that she shall be broken up.

IT IS SUBMITTED no further action is necessary.



© 2020

17.7.50.

Lloyd's Register Foundation

W1031-0344

The vessel has now been towed away from Immingham to the River Tyne where it is stated the vessel will be broken up.