

Lloyd's Register of Shipping.

FOUNDED 1760.

RE-CONSTITUTED 1834.

No. 22095
135

No. 71, Fenchurch Street, E.C.3

LONDON, 11th April, 1949

This is to Certify that the
" Cygnet "
Steamer
3726 Tons, of Panama
Built at Stockton in March, 1911
has been surveyed at Piraeus by the Surveyors
to this Society, and reported to be, on the in December, 1948 and January, 1949
in such fit and efficient condition as is prescribed by the Society's Rules for
the safe carriage of dry and perishable or other approved cargoes, and that she
No. 56237 has been continued as CLASSED in the REGISTER BOOK of this
Society, with the Character **100A1** subject to Periodical Surveys

as required by the Rules, also to shell plates E.1 (port and starboard) being renewed at the next
dry docking and not later than January, 1950, to a lower anchor being tested at the earliest opportunity
and to a lower anchor of proper weight and test being supplied. Cargo battens not fitted.

(See Endorsements Overleaf)

Specially Surveyed, January, 1949

Witness my hand,

Herbert A. Kelly

Chairman.

of the Committees of Classification.

R. J. L. L. L.
1720 Secretary.

This Certificate is issued upon the terms of the Rules and Regulations of the
Society, to which Owners are referred, and which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions
of the Society are properly executed, it is to be understood that neither the Society nor any
Member of any of its Committees is under any circumstances whatever to be held responsible for
any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry
in the Register Book or other publication of the Society, or for any error of judgment, default or
negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or
Agents of the Society."

W1031-0351

ENDORSEMENTS.

The following items relating to the condition of this ship have been noted, but do not affect the maintenance of Classification.

The bottom is slightly set up.

RS



© 2020

Lloyd's Register
Foundation