

Was a damage report made by anyone else? If so, by whom?


Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? yes

URGENT


W. Anderson -

- GRANNY SUZANNE -

Staze check the attached drawings - The vessel was originally built to Germanischer Lloyd ^{requirements} and was latterly classed with the B.C. - A new boiler was fitted in 1931 which was constructed to L.R. class.



26.1.48 © 2020



Lloyd's Register
Foundation

WIP 32 0251

Tried main engine, auxiliary machinery and pumping arrangements under working condition good.