

V.

1,9,44.

2-MAY-1945

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME "MUDO" REPORT Ips. No. 112691

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Notation of "Examined L.R. 8.44 has been withheld pending machinery survey.

Permanent repairs are required to buckled stem and bulwark plating (s.s.f) indented bulwarks etc. (p & s) and to slightly buckled frames in holds (p & s) at the Owners' convenience.

The IPSWICH Surveyors report the vessel placed in dry dock, bottom coated a further "General Examination" held, renewal to keel plating, ceiling under hatchways and repairs effected to the windlass.


It is submitted the vessel is eligible to have her present records maintained with record of docking date 2.45 subject as above and to have the notation of "Examined 4.45" valid for 12 months assigned.

(Docking date) Subject.
2.45 Lwt.)

"Examined L.R. 4.45"

Wals

24.4.45



© 2020

Lloyd's Register Foundation