

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

30 APR 1948

VESSEL'S NAME NIRVANA

REPORT Madras
CalNo. 52
E3280

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

This ship has notation of "Examined 11,47" valid for six months.

For conditions of class, see previous endorsement.

It is reported this ship is definitely scheduled for scrapping on completion of her present class validity in May next. (See memo dated 2.2.48).

The MADRAS Surveyor reports, 2,48, ship afloat, and temporary repair (cement) of shell in way of boiler blow down valve, (p.s.) specially examined and found efficient.

The CALCUTTA Surveyors report, 3,48, ship afloat, and temporary repairs effected in way of 4th and 5th strake below sheer in No.1 hold (p.s.) specially examined and found efficient for voyage to U.K.

IT IS SUBMITTED this ship is worthy to remain as classed, subject to set over stem and stem plating being permanently repaired and tank top ceiling in No.3A hold renewed at the first opportunity, to permanent repairs to engine room aft bulkhead base plate (p.s.), Nos.2/3 hold bulkhead wing plate (s.s.), Nos.6/7 D.B. tank division (s.s.), shell plating in way of boiler blowdown valve (p.s.) and indented shell plating etc (s.s.) by 5,48, and to bulwark plating (p.s.f.), shell frames (p & s) in Nos.2,3 & 4 holds and cross bunker, 3rd deck plating (p.s.) in way of fore end of No.4 hold and Shelter Deck plating (p.s.) abreast mainmast being dealt with at the Special Survey, and to permanent repairs to indented shell plates etc (p.s.f.) on ship's arrival at U.K. ~~from present voyage~~ from present voyage, also to (a bower anchor and 30 fathoms of chain cable being supplied).

As now, Subject.

In S.R.L.

Special Survey (D) to be held by 5,48.

PLATING TO BE DRILLED
AT NEXT S.S.

Amend S.R.L.

29
H
48



© 2020

Lloyd's Register
Foundation