

20/11
s/o Rivana

W. Gray & Co No 847

It is submitted the Surveyor should be
informed in reply to his letter that he should
satisfy himself by testing with a hose and
other means, that the cargo port doors are
tight so as to be perfectly watertight as stated
in the approved plan.

8/9/14.

GRM

28/9/14



© 2020

Lloyd's Register
Foundation

intersection of the wood or iron deck with side.