

Orion

1

Sent to Chief Surveyors *18/8/09* Received from Chief Surveyors
 VESSEL'S NAME *St S Glenchil* Report *Is* No. *28004*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey *Just entry* When due

+ 100 A1 (Stub) Spar deck
1st (2nd) Spar deck (2nd) & dup framing
N.B. Bull DB a 118 u 8 x 350 f 180 10674 D-Ta 34 8786 APT296
E.K. 68H Ben Lloyas 9100 P37 B120 FHH

For Rell
18/8/09



© 2020

Lloyd's Register Foundation

" Angles on upper edge	<i>48</i>	<i>48</i>	<i>48</i>	<i>48</i>	" Deck, Material and thickness <i>Steel</i>	<i>38</i>
" Spacing	<i>25/8</i>	<i>25/8</i>	<i>25/8</i>	<i>25/8</i>	Forecastle Deck Stringer Plate, b'dth & th'kns	<i>38 x 3/2</i>
PILLARS, In 'tween Deck, size and spacing	<i>25/8</i>	<i>25/8</i>	<i>25/8</i>	<i>25/8</i>	" Angle on ditto	<i>2</i>
	<i>48</i>	<i>48</i>	<i>48</i>	<i>48</i>	" Tie Plates	<i>5 x 3/2</i>