

respecting this case.

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined **YES, NOT DESIRED.**

Society's Freeboard (if assigned) as painted on

ES FOR UN

lm.1241.

1

ent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME AIRCREST

REPORT

GLS.

No. 65089

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey DAMAGE

When due

Subject to ceiling being fitted under hatchways at the first opportunity and to (a bower anchor and 45 fathoms of chain cable being supplied.)

(H.W)

Wal
24.2.42

No Correspondence
6/62
QR



© 2020

Lloyd's Register
Foundation

W1037-0208

Have the Tanks been tested? No

Doubling Plates under Sounding Pipes " "

Salting (State if examined.)

Standing and Running Rigging

Sein

General Observations Opinion as to Class. Recommendation, &c.: