

Are they fixed sufficiently high on the ship's side to be seen without lifting the stokehold plates

Are the Discharge Pipes above or below the de

W1038-0019

Engine No. *A. 154 M.S.M.* Made by *Markham & Co.*  
~~Boiler~~

For

*Sheffield* Report No. *527*


It is submitted that ~~a copy of~~ this Report be  
~~forwarded~~ to the ~~Surveyors for their~~  
~~returned~~ ~~guidance and for completion.~~  
*retained in this office*  
*pending allocation of the engines to a*  
*specific vessel.*

Date

Original Report now sent to.

1m 10.40.

*Sunderland see letter dated 1/6/45*



© 2020

Lloyd's Register  
Foundation