


S.S. "EMPIRE MOMBASSA" A/MS.968.  
Shipbuilding Corporation (Wear) No.7 Markham  
& Co. Engine No.A/MS/M.154.

---

Enquiry from the Admiralty ~~D.D.M.B.~~ D.M.S.R.

IT IS SUBMITTED that since the 'heating-up'  
of a piston rod during the first trial of the engine  
is not an infrequent occurrence, no explanation is  
required and it should be sufficient if a copy of the  
Surveyors' letter be forwarded to the Admiralty.



20.8.45.

*L-22/8*



© 2020

Lloyd's Register  
Foundation

W1038 - 0028