

The SWANSEA Surveyors report (11.49) the vessel examined as far as practicable afloat after grounding and Nos. 1, 2 & 3 D.B. tanks found to be making water. They recommend the vessel be placed in dry dock at Port Talbot. being considered efficient


Two s are

SWANSEA.

"BARRY CASTLE" 24421. As recommended.

24402,43. As recommended.

24438,46 "WATSON FERRIS" The contents of your reports are noted and a notation of "Laid up pending repairs", has been assigned.



© 2020

Lloyd's Register
Foundation

4.1

For ~~GO~~ Dept.
Please return to
"S" Dept.



© 2020

Lloyd's Register
Foundation