



BRITISH  
CORPORATION  
REGISTER.

Addeley Street,  
CAPE TOWN, 5th July, 1949.

ed side, found  
ldth, riveted a

m, 9, 43.

DCW

11 JUL 1949

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME STAL

REPORT Alx.

No. 3889

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

For conditions of class see previous endorsement.

The ALEXANDRIA Surveyor reports (6.49) the vessel afloat and, on account of wear and tear, repairs (welded doubler) effected to wasted and holed shell plate No. 3 from aft in 2nd strake below sheer (s.s.). The Surveyor recommends this plate be renewed at the Special Survey.

Wasted rivets in No. 4 plate from aft, 1st strake below sheer (s.s.) also renewed.

IT IS SUBMITTED the vessel is eligible to remain as classed subject to rudder post (E.W. 7.48) being specially examined, and to bow plating (p.s.) and set up keel and bottom plating (s.s.) being specially examined and dealt with as necessary, at the next drydocking, also to shell plate No. 3 from aft in 2nd strake below sheer (s.s.) being renewed by the next Special Survey.

As Now, Subject  
Amended.



© 2020

Lloyd's Register  
Foundation

W1039-0075

ons at present