

Dear Sirs,

WOKINGHAM COPY.

MLT

LLOYDS REGISTER NEW YORK

(3.2.43).

808 CLASSIFICATION CONTEMPLATED AND EXAMINED ELEVEN FORTYTWO BOILER SURVEY  
EVEN FORTYTWO ASSIGNED ELECTRICAL EQUIPMENT REQUIRES EXAMINATION AND MEGGER  
STOP STOP TO COMPLETE CLASSIFICATION DOUBLE BOTTOM TANKS ONE TWO THREE SIX  
FIVE NINE AND AFTER PEAK TANK TO EXAMINE INTERNALLY WITH DOUBLING PLATES  
UNDER SOUNDING PIPES STOP NUMBER SIX AND AFTER PEAK TANKS TO TEST AND BUNKERS  
FIVE SPACE BELOW FLOOR TUNNEL TUNNEL WELL PUMPS AND WATERTIGHT DOORS TO  
EXAMINE PARTICULARS REGARDING ORIGIN WEIGHT AND TEST OF ANCHORS AND CHAIN  
PLATES ALSO SCANTLING ONE AFTER PEAK BULKHEAD ARE REQUIRED STOP NO PART OF  
THE SURVEY HELD STOP REPAIRS REQUIRED TO LAGGING OF BOILERS AND STEAMPIPES  
ON SHAFT TO EXAMINE NEXT DRYDOCKING



© 2019

LLOYDS REGISTER  
Lloyd's Register  
Foundation

W104-0090