

Register Tonnage 1020, 11

1st Longitudinal Number (L x D) = 3835

2nd. Numeral L x (B + D) = 16315

Managers Tank Steam Co.
(Where necessary to be entered in Reg. Book.)

WID42-0077

5c, 9, 30.

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *S.S. T.S. M/V ANGELINA*Rpt. *Ans* No. *12375*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

P. Long

Transverse No.

3835

Depth "d"

Framing: Table No.

Description *Longitudinal framing at bottom and top of trunk.**2* Longitudinal No.*16315*

Proportions

Length

11.51 to top of trunk

Depth =

Deck Sheerstrake

*as approved.**Revised Rules.*

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✠ 100 A.I. (Steel). Carrying Petroleum in Bulk.

10" (Std) Longitudinal framing at bottom and at top of trunk

Cell D.B. & E 48' 8" E, F.P.T. 275, A.P.T. 1075.

F.K. 9 B.H., 2 cm, Lloyds A CP.

P 84, TRUNK 129', F 47.

*machs apr.*50x45x5
30x90x11
90x45x11
rather all

660 m



© 2021

Lloyd's Register
Foundation

DOUBLE BOTTOM. IN MOTOR ROOM.

Solid Floors, thickness and spacing

3m
on floor spaced 660 m

Are Frame and Reversed Frame

ordinary

TRUNK

Bridge Deck, Angle, E or [see Rpt. I.]

Spacing

50x45x9/2
660

For A.O.

—

THE OFFICE OF THE SURVEYOR GENERAL
OF THE LANDS OF THE UNITED STATES
WASHINGTON, D. C.



© 2021

Lloyd's Register
Foundation



REGISTERED

Total
Gross Tonnage
Register Tonnage

TERDAM DISTRICT
SURVEYOR

DOUBLE BOTTOM
Solid Floors,

Bracket Floor