

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

17th August, 1931.

Dear Sirs,

With reference to your Report No.12375 on the Electric Fittings of the s.s."ANGELINA", it is concluded that all the electric cables are lead covered in addition to being armoured, but I shall be glad if you will let me know whether this is so.

I am, Dear Sirs,

Yours faithfully,

Secretary.

The Surveyors,
AMSTERDAM.



© 2021

Lloyd's Register
Foundation

5.
e.

they

is

0082

ble {
in }
... }
hips }
or {
ngle }
..... }
.....
.....
.....
.....
.....

DOUBLE BOTTOM. IN MOTOR ROOM	Angles	Spacing.....	TRUNK
Solid Floors, thickness and spacing	Bridge Deck, Angle, E or [see P. 11, I.....
	<i>8.5m space 6.6m</i>		