





Rp

Dates of Survey while building  
During progress of work in shops - -  
During erection on board vessel - - -  
Total No. of visits 9

1/6 5/8 21/2 1/9 13/9 15/9 23/9 10/10 15/10 1930.

Framin  
Frames  
Frame: De

Dates of Examination of principal parts—Cylinders 11/6 - 25/9 Covers 11/6 - 15/9 Pistons 5/2 - 13/9 Piston rods <  
Connecting rods 5/2 - 13/9 Crank and Flywheel shaft 11/6 - 23/9 Intermediate shaft <  
Crank and Flywheel shaft, Material Steel Identification Mark F.S. 451.13.5.30 Intermediate shafts, Material L Identification Marks <

Is this machinery duplicate of a previous case No. If so, state name of vessel <  
In approved plans See Engine No. 1544.

General Remarks (State quality of workmanship, opinions as to class, etc.)  
The engine has been constructed in accordance with the Rules, Secretary's letter and approved plans.  
All matters tested as required and workmanship good.  
The engines have been tested under full working conditions on bench and good.

This engine has been forwarded to  
N. v. Bungehuis's Machine Fabric, Scheepweg  
Rotterdam.

The engine has been placed on board and examined under working condition and found in order.

*[Signature]*

Sp  
Lon  
F  
F  
Doc  
Bet  
L  
B  
Spa  
B  
S  
Up  
E  
Up  
S  
STE  
S  
STR  
st  
U  
Pool  
BRID  
FOREC  
Total  
MIDSI  
COLLISION  
AFTER PE  
STEEL

Im. 7. 26 - Transfer.  
(The Surveyors are requested not to write on or below the space for Committee's Minutes.)

The amount of Fee in £ 200.- : When applied for, 19  
Travelling Expenses (if any) £ 4.- : When received, 10-11-30

Surveyor to Lloyd's Register of Shipping.

Committee's Minute  
Assigned

TUE. 27 JAN 1931

See Rot. J.E. 19996



© 2020

Lloyd's Register  
Foundation