

F.E.

Received by Chief Ship Surveyor *14/10/12*

Received from Chief Ship Surveyor

VESSEL'S NAME *At St Channel Queen* Rpt. *File* No. *2534*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

BAYNAIN

Transverse No. *41.29*Depth "d" *12.08*Framing: Table No. *3 page 10*Description *as approved*Longitudinal No. *7225*Proportions Length = *8.46*
DepthBridge Deck Sheerstrake *as per Rules*

RETAIN

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed *+ 100A-1. (2nd)* as recommended.

*+ 100A-1. (2nd)**1st (2nd). "Mud deck"**MB. DBa 29 28t FRT 42t APT 30t**BR 7" H3H Cmn. Lloyd's at 60. P19 Q33 BS1 F36*

© 2020

RBN

Lloyd's Register
Foundation

W1044-0216