

5 - JAN 1940

Inspected by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME "BEYERLAND"

Rpt. Gro. No. 84

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The Groningen Surveyor reports this vessel examined afloat after grounding, soundings taken and no signs of leakage or damage found. The Surveyor, however, recommends further examination in dry dock at the first convenient opportunity.

It is submitted action be deferred accordingly.

Insert in S.R.L. Dry docking (grounding)

was
5-1-40

[Signature]
W



© 2020

Lloyd's Register
W1044-0229
Foundation