


Method of reversing Engines By compressed air Is a governor or other arrangement fitted to prevent racing of the engine when declutched Yes
No. 1466
Thicknes of cylinder liners 25.5 mm Are the cylinders fitted with safety valves Yes Are the exhaust pipes and silencers

Engines No. 85696 } Made by A.B. Atlas - Sieel
87712 }
33204 } " " A.B. Bolinder - Munkstall
Pitcher Van der Giessen & Lozer Scheepw. h.v. (N.S. "Beyerland")

Spec. Report No. 4983

It is submitted that a copy of this Report be forwarded returned to the Rot. Surveyors for their guidance and for completion.

Date 14/10/39 2-4



Pipes, Cocks, Valves, and Pumps in connection with the machinery and all boiler mountings accessible at all times
Arrangement of valves and their connections such as to prevent the possibility of water passing from the sea or from water tanks into the cargo or m