

liners are fitted, is the shaft lapped or protected between the liners
 as per rule 7.98 ✓ Dia. of Crank shaft journals as per rule 8.38 ✓
 Dia. of Tunnel shaft as fitted 7.98 ✓ Dia. of Crank pin as fitted $8.3/4$ ✓ Size of Crank webs $17\frac{1}{2}$ ✓
 collars $2\frac{3}{4}$ ✓ Dia. of screw $1\frac{1}{2}$ ✓ Dia. of screw $1\frac{1}{2}$ ✓

Trawler. "Islande"

Hul 37025.

It is submitted, before this case receives consideration, the Caen Surveyor should be requested to state whether he has tried the working of the bilge & tank suction & the reversing engine & seen the donkey check valve overhauled as advised by the Hull Surveyors & whether these parts are now satisfactory.

W.D. P.M.S.
 1/6/26.

Lloyd's Register

W1045-0035

Date of test 8-3-26

Can each boiler be worked separately ✓

Area of fire grate in each boiler 80 sq ft ✓
 70 m.m. dia. ✓

Area of each valve 5.94 sq ✓ Pressure to which they are adjusted 180 lb ✓