

*Subject to indented plating (P. & S.) being dealt with at
the first favourable opportunity*

5 APR 1940

11

Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME

CORTELLAZZO

Rpt. TRI.

No. 12857

Marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Survey

DOCKING

The

Trusto

Surveyors report this vessel placed in

dry dock, bottom cleaned and coated, ~~repairs or renewals to~~
~~and minor repairs effected.~~

Indented plating, as above, examined & found efficient

It is submitted the vessel appears worthy to remain as
classed with record of survey 3-40 as recommended, *subject as above*

100 A.I.

with food

3-40 TRI.

(Pilled for carrying out etc)

Subject, etc

W.S.
3-4-40



© 2021

Lloyd's Register
Foundation